

Dean L. Sicking, Ph.D., P.E. 2004 Roadside Safety Workshop June 23-24, 2004





Design Problem No. 4

TH 4 criteria

Rural 2-lane undivided highway

- 12' lanes
- □ 10' shoulders (2' bit., 8' aggr.)
- □ ADT = 2,100
- \square Design speed = 60 mph
- \square Posted speed = 55 mph



Design Problem No. 4 (Continued)

- Resurfacing scheduled for 2005
 3" mill & 3" overlay
- Guardrail upgrades
 - □ West of bridge 46003 are straightforward
 - Between bridges 46003 and 932 are less clear





tes

Distance: 4186.7 ft Latitude:+43.6483803 Heading: 79.3° District: 7 Name: M4 FDiPost: 10.111 SurveyDateTime: 05/27/2003 14:58 Mile Point: 10.940 RP Longitude:-94.7584686 Grade-CS: Co: 0 DD: I TDiPost: 10.990



Bridge 46003

Distance: 4237.5 ft Latitude:+43.6484070 Heading: 79.6 District: 7 Name: M4 FDiPost: 10.111 SurveyDateTime: 05/27/2003 14:58 Mile Point: 10.950 RP Longitude:-94.7582779 Grade-CS: Co: 0 DD: I TDiPost: 10.990



tes

Distance: 4485.8 ft Latitude:+43.6485252 Heading: 79.7 District: 7 Name: M4 FDiPost: 10.111 SurveyDateTime: 05/27/2003 14:58

Mile Point: 10.997 RP Longitude:-94.7573471 Grade-CS: Co: 0 DD: I TDiPost: 10.990



test

Distance: 4584.6 ft Mile Point: 11.015 RP Latitude:+43.6485748

Latitude:+43.6485748 Heading: 80.0" District: 7 Name: M4 FDiPost: 10.111 SurveyDateTime: 05/27/2003 14:58 Mile Point: 11.015 RP Longitude:-94.7569885 Grade-CS: Co: 0 DD: I TDiPost: 10.990



test

Distance: 293.4 ft Latitude:+43.6487160 Heading: 80.1 District: 7 Name: M4 FDiPost: 10.990 SurveyDateTime: 05/27/2003 14:59

Mile Point: 11.056 RP Longitude:-94.7558746 Grade-CS: Co: 0 DD: I TDiPost: 11.979



Bridge 932

Distance: 541.7 ft Latitude:+43.6488342 Heading: 79.5" District: 7 Name: M4 FDiPost: 10.990 SurveyDateTime: 05/27/2003 14:59 Mile Point: 11.103 RP Longitude:-94.7549515 Grade-CS: Co: 0 DD: I TDiPost: 11.979







Design Problem No. 4 (Continued)

- Existing guardrail
 - 3-cable guardrail
 - Protects deep ditch adjacent to highway
 - □ 2:1 slope

What type of guardrail would work best between bridges 46003 and 932?

3-Cable Guardrail on 1.5:1 Slope







Computer Simulation Results

Reduced post spacing to 4'

 Increased lateral stiffness
 Reduced lateral barrier deflections

 Increased barrier offset to 4' from breakpoint

 Limited vehicle penetration on slope
 Reduced vehicle c.g. drop



Design Problem No. 4 Conclusions

- Cable guardrail not acceptable within 1' of 1.5:1 slope
- For steep slopes use 4' post spacing and install barrier atleast 3' from slope breakpoint
- Rounding slope breakpoint will improve barrier performance