



Design Problem No. 1





Dean L. Sicking, Ph.D., P.E.
2004 Roadside Safety Workshop
June 23-24, 2004





Midwest Roadside Safety Facility

Design Problem No. 1

- Facts
 - 6-ft deep pond near and/or within clear zone
 - culvert at upstream end of pond
 - three cable barrier used to protect entire obstacle, including portions outside of clear zone
 - 10:1 approach slope to cable barrier
 - slope, varying from 2:1 to 5:1, begins 2-ft behind cable barrier posts
 - no accident history






Midwest Roadside Safety Facility

Treatment of Ponds Near Edge of Clear Zone


- **Comments**
 - three cable barrier incapable of redirecting 2000P vehicle impacting at TL-3 condition of NCHRP 350 when installed adjacent to 1.5:1 slope
 - TL-3 approved, strong-post, W-beam design variations exist when placed near or directly on 2:1 fill slope



 *Midwest Roadside Safety Facility*

Design Problem No. 1 (Continued)

- **Conclusions**
 - could conduct benefit-cost analysis to determine whether entire hazard required protection
 - extending protection to include entire hazard is reasonable and appropriate due to small increase in guardrail length
 - if MnDOT treats hazards entirely outside of clear zone, agency wide policy should be adopted
 - potential tort risk associated with inconsistent application of clear zone principles

 *Midwest Roadside Safety Facility*

Recommendations

- Cable guardrail may function in this application, but research not yet complete
- Simulation study indicates cable barrier should provide acceptable performance when placed 3' in front of slope break point and post spacing reduced to 4'
- W-beam guardrail with 7' posts on 3'-1.5" centers placed at the slope break point is an NCHRP Report 350 approved alternative