





## December 2020 ADDENDUM / ERRATA

## to MwRSF Report No. TRP-03-440-20 "MASH Full-Scale Testing of Single-Post, U-Channel Sign Supports" Published November 10, 2020

Page 31	Removed MASH 2016 lateral Occupant Impact Velocity (OIV) limit from Table 10
63	Revised the MASH 2016 OIV limits in Table 16
64 – 66	Revised the MASH 2016 OIV limits in the Transducer Data tables
69	Removed MASH 2016 lateral OIV limit from Table 17