

December 2023 ADDENDUM / ERRATA

to MwRSF Report No. TRP-03-211-09

“Development of a TL-1 Timber, Curb-Type, Bridge Railing for Use on Transverse, Nail-Laminated, Timber Bridges”

Published May 6, 2009

Page

53

Revision

Part number for washers corrected from “a8” to “b7” on system drawing.